



THE SOLUTION

The solution is to mark the sealing surface of the gasket at fixed intervals when the gasket is being manufactured.

Utilizing Northern box culverts, and Press-Seal gaskets (with PEMs) a 55+ psi reading was maintained for 3 minutes.







