




2022 ACPA Chairman's Safety Award Finalist: Rinker Orlando – Dip Tank Bar

Moving the headers from the dip tank to the machine would leave a slippery trail of oil on the floor.

We welded two flat bars to one of the rails to rest the header and allow it to drip for a few minutes before placing it on the pipe. It also improved the appearance of the spigot.



For more information contact:
Israel Cedillo
Israel.cedillo@rinker.pipe.com
(407) 443-4714