



The Power of Water is Impressive So Are Durable, Reliable Precast Concrete Box Culverts



READ THE ARTICLE



Gladwin County, MI, Wildwood Road (bermed roadway) was compromised during a 500-year flood event in May 2020.



Stone was quickly brought in to stabilize the road and allow water to only flow through the precast concrete box culvert into Secord Lake.



The Weight and Strength of the Precast Concrete Box Culvert kept Wildwood Road in place and prevented further flooding.



Severe flooding following the failure of the Edenville and Sanford Dams.



When the Edenville Dam failed during this rain event, it emptied 21.5 billion gallons of water downstream and emptied the lake in one hour.

When Gladwin County Road Commission replaced a failing CMP culvert with a precast box culvert under Wildwood Rd. in 2017, the precast box culvert endured the strength of the 500-year flood event in 2020 and prevented the 815-acre Secord Lake and Smallwood Lake from overflowing their berms, therefore preventing even more flooding than was originally experienced.