



Hopper Doors Improvement Green Bay, WI – Century Rd. Plant

Before:




After:




Benefits:

- Team members are no longer in danger of slipping
- Heavy lifting of hopper doors has been eliminated
- Team member operating hopper doors is safely behind a barrier

New heavy-duty wheels were also added to handle tough, outdoor conditions.



Problem:
Sand and gravel bin doors had to be opened by hand which can be heavy and cause strains. Snow and ice could also cause the surface to become slippery



Solution:
Wetcast team members got together and created a mechanical lifting design

